

Main Spindle Drives - Accessory

Tool-changing station for HSAW spindle motors



Scope of delivery:

- pneumatic connecting panel
- hose, 3 m
- tool-changing station (without collets holder)

| Tool-changing station | Item no. |
|----------------------------------|-------------|
| Tool-changing station x4 | 239011 0040 |
| Tool-changing station x5 | 239011 0050 |
| Tool-changing station x10 | 239011 0100 |

| Collets holding individually | Item no. |
|----------------------------------|-------------|
| SK 20 (collets 3-10 mm) | 239122 |
| SK 20 (collets 3-12.7 mm) | 239122 9000 |

Linear changer HSK 25 for HSFW-150 spindle motor



Scope of delivery:

- pneumatic connecting panel
- hose, 3 m
- tool-changing station (without collets holder)

| Tool-changing station | Item no. |
|----------------------------------|-------------|
| Tool-changing station x5 | 239011 0051 |
| Tool-changing station x10 | 239011 0101 |

| Collets holding individually | Item no. |
|----------------------------------|----------|
| HSK E25 (collets 1-10 mm) | 477125 |

Direct tool changer for HSAW 2.05-SDF upon request